

EDT Surrey Ltd

Contact Information

Name: Ray Punter
Address: Walton-on-Thames, Surrey, KT12 2HG
Telephone: 01932 232600
Mobile:
Email: edtsurrey@btconnect.com
Web: www.edtsurreyltd.com

Checkatrade Monitoring

Member Since: **23 November 2005**
Membership Number: **85366**

About this Tradesperson

Limited Company: **Registration no. 6959413** VAT registered: **No. 881039421**
Public Liability insurance: **Current - Verified on 7 November 2011** Cover Amount: **1,000,000**
Insured by: **Zurich Insurance**
Accreditations: **RVM**

Most Recent Customer Feedback

Survey for driveway problems/new damp proof course. 10 / 10
Really professional and honest, no pressure into having work done that wasn't needed. Great advice given. Would use/recommend for future. **Customer in West Byfleet, 30 April 2012**

Survey was done on a leak 10 / 10
Professional advice and great honesty in service. **Customer in London, 26 April 2012**

Advice on getting rid of damp free survey of wall affected. 9.5 / 10
Mr Punter was helpful with advice and courteous
- he rang ahead because he was running 10 minutes late. **Customer in West Molesey, 1 April 2012**

House treated for woodworm 10 / 10
Working with EDT Surrey went really smoothly - from the initial call to the work carried out. When we found out we had to get the house treated for woodworm I searched on Checkatrade for companies in our area. EDT Surrey were really helpful on the phone, and sent their surveyor, Ray Punter, over to our house within a few days of the call. Ray confirmed the woodworm problem, and sent through a quote and a comprehensive report within 2 days after the survey. The quote was very reasonable and we agreed a date for the house to be treated. EDT were punctual, left the house tidy, and shortly after the work was completed they sent us the certificate to confirm treatment. Overall we were really happy with the work, and would recommend this company. **Customer in Windsor, 19 March 2012**

Advice on suspected rising damp problem. 9 / 10
Ray said we didn't have rising damp, pointed out what was causing the damp problem and gave specific instructions on remedial work, we will be able to carry out ourselves. **Customer in Aldershot, 9 March 2012**



